

121 GOLDTHWAITE STREET

121 GOLDTHWAITE STREET

115 GOLDTHWAITE STREET

STREET

GOLDTHWAITE

PF

SIDE



426 MARTHA STREET







103 GOLDTHWAITE STREET

# NORTH SIDE OF MARTHA STREET



AERIAL NEIGHBORHOOD PLAN





600 MONTGOMERY STREET

453 MARTHA STREET



Barganier Davis Williams Architects Associated

Drawing Tille:

**DTHWAITE** 

SIDE

**EAST** 

NEIGHBORHOOD PHOTOGRAPHS

5-3-2021 AS NOTED

A0.1



43 GOLDTHWAITE STREET



43 GOLDTHWAITE STREET



413 MARTHA STREET




415 MARTHA STREET



423 MARTHA STREET







NORTH ELEVATION







B, REMOVE VEGETATION AND SOIL FROM FACE & TOP OF BRICK RETAINING WALL C, REMOVE MASONRY STEPS AND ASSOCIATED FOUNDATION TO BELOW FINISH GRADE

D. REMOVE GARAGE CONSTRUCTION IN IT'S ENTIRETY,
SALVAGE APPLICABLE MATERIALS FOR RE-USE IN NEW
CONSTRUCTION, SALVAGE MATERIALS TO INCLUDE, BUT
NOT LIMITED TO, WOOD TRIM, BRICKS, ETC.
E. REMOVE WOOD GATES AND FENCING

**GENERAL NOTES** 

F. REMOVE TREE AS APPROVED BY THE URBAN FORESTER, GRIND STUMP TO BELOW FINISH GRADE

G. REMOVE EXISTING CONCRETE STEPS AND LANDING

H. PARKWAY TREE TO BE REMOVED BY THE CITY OF MONTGOMERY



Barganier

624 South McDonough Stree Montgomery, AL 36104



HE BENJAMIN WINSTON
WALKER HOUSE
103 GOLDTHWAITE STREE
MONTGOMERY, ALABAMA 36104



Scale: Drawing Title:

> DEMOLITION PLAN

AS NOTED

A0.2

DESIGN DOCUMENTS




WEST ELEVATION

SCALE: NONE








MARTHA STREET





INTERIOR TREE

INTERIOR TREE



SITE & LOWER LEVEL PLAN

SCALE: 1/8" = 1'-0"

### **GENERAL NOTES**

- CONTRACTOR TO VERIFY EXISTING CONDITIONS PRIOR TO ANY FABRICATION OR CONSTRUCTION.
   CONTRACTOR TO NOTIFY ARCHITECT OF ANY DISCREPANCIES AND OBTAIN OWNER APPROVAL FOR ANY CHANGES

### KEYNOTES

- NEW BRICK VENEER WALL. RE-USE BRICK SALVAGED FROM DEMOLITION OF GARAGE AND RETAINING WALLS
   NEW BRICK VENEER LANDSCAPE WALL, FENCE AND GATE, RE-USE SALVAGED BRICK FROM DEMOLITION OF GARAGE & RETAINING WALLS. PROVIDE NEW LIMESTONE CAP. NEW WROUGHT IRON STYLE DECORATIVE FENCE, ANODIZED "BLACK", REFER TO ELEVATIONS
- 3. NEWWROUGHT IRON STYLE DECORATIVE GATE, ANDDIZED "BLACK", REFER TO ELEVATIONS
  4. NEW72" HIGH DECORATIVE WOOD PRIVACY FENCE, STAINED "CEDAR" WITH 48" WIDE ACCESS GATE. REFER TO ELEVATIONS

  TO THE PROPERTY OF THE PROPERTY
- 5. NEW CONCRETE & CONCRETE BLOCK FOUNDATIONS
- 6 NEW CONCRETE STAIRS & LANDING WITH DECORATIVE HANDRAIL HANDRAIL PAINTED BLACK
- 7. NEW 24" x 24" CONCRETE PAVERS
- 8. NEW PVC COLUMNS AND GUARDRAILS, PAINTED "WHITE"
- 9, NEW CONCRETE SIDEWALK AND CONCRETE STEPS



Barganier Davis Willtams Architects



624 South McDonough Street Montgomery, AL 36104

phone: 334.634.2036

HE BENJAMIN WINSTON
WALKER HOUSE
103 GOLDTHWAITE STREE
MONTGOMERY, ALABAMA 36104 뿐

RESTORATION & ADDITION

	. Description	Date
٨	ISSUED FOR RE	VIEW 05/03/2
Pre	oject No.	2021-105
Drawn By:		BDW
Date:		5-3-2021
Scale:		AS NOTED

SITE & FLOOR **PLANS** 

A0.3





THE

HE BENJAMIN WINSTON
WALKER HOUSE
103 GOLDTHWAITE STREE
MONTGOMERY, ALABAMA 36104

RESTORATION & ADDITION


Barganier Davis Williams

MonIgomery, AL 36104

phone: 334.834.2038

**EXTERIOR ELEVATIONS** 

A0.4



MARTHA STREET



Barganler Davis Williams Architects Associated



phone: 334,634,2038 www.bdwarchilects.com



RESTORATION & ADDITION TO

THE BENJAMIN WINSTON
WALKER HOUSE
103 GOLDTHWAITE STREE
MONTGOMERY, ALABAMA 36104

No. Description	n Dat	
Project No.	2021-10	
Drawn By:	BDV	
Date:	5-3-202	
Scale:	AS NOTED	

Drawing Title:

TREE
REPLACEMENT
PLAN

A0.2.1







**EXISTING WEST ELEVATION** 



**EXISTING WEST ELEVATION** 

#### **KEYNOTES**

- PRESSURE WASH AND APPLY RUBBED CONCRETE FINISH OVER EXISTING STUCCO WALL FINISH WALL TO BE PAINTED.
   REMOVE EXISTING STEPS. INSTALL NEW STEPS WITH RAILING AS DETAILED.
- AS DE INILEU.

  A PRESSURE WASH AND APPLY RUBBED CONCRETE FINISH TO STEP WALLS. FINISHED WALL TO BE PAINTED. INSTALL NEW CAP MATERIAL ON WALL AS DETAILED.

  CLEAN AND REPAIR EXISTING DOMED TIN METAL ROOF AND SLOPED PORCH ROOF AND APPLY NEW ROOF COATING. SEE

- SPECS

  REPLACE ALL WINDOW SASHES WITH NEW VINYL CLAD WOOD SASHES, UNLESS NOTED OTHERWISE

  REPAIR ALL EXISTING STUCCO WALL FINISHES ON THE EXTERIOR, INCLUDING REPAIRING ORACKS, REPLACING MISSING STUCCO, REPAIRING OUTSIDE CORNERS.
  REPAINTING OF THE STUCCO SHALL INCLUDE ONE COLOR FOR THE FAUX STONE AND ONE COLOR FOR THE TOOLED FAUX MORTAR JOINTS, SIMILAR TO THE ORIGINAL DESIGN.

  REPLACE MISSING STEERING BUILDER TO THE TOOLED FAUX MORTAR JOINTS, SIMILAR TO THE ORIGINAL DESIGN.
- REPLACE MISSING EXTERIOR RAIL COMPONENTS TO MATCH EXISTING,
   SEE DRAMMINGS FOR DESIGN OF FRONT AND SIDE PORCH COLUMNS, BRACKETS, BEAM, ETC,
- CULUMMS, BRACKE IS, BEAM, ETC.

  9. REROOF ENTIRE BUILDING WITH NEW ARCHITECTURAL
  ASPHALT SHINGLES SEE SPECS, PROVIDE ADD ALTERNATE
  FOR SYNTHETIC SLATE SHINGLES SEE SPECS, REPLACE
  ROTTEN DECKING ENCOUNTERED, PARTICULARLY ARCUND
  CHIMNEYS.

  10. REMOVE BRICK RETAINING WALL ON SOUTH ELEVATION AND
  RECONSTRUCT PER DETAILS, REUSE EXISTING BRICK.
- 11. REMOVE EXISTING CONCRETE STEPS.
- CLEAN, SCRAPE AND REPAINT ALL EXISTING WOOD SIDING AND TRIM AFTER REPAIRS ARE MADE.
- 13 REFLASH ALL CHIMNEYS
- 14. CLEAN, REPOINT AND SEAL ALL BRICK VENEER TO REMAIN
- 15 REMOVE EXISTING TREE
- 16. EXISTING CARRIAGE HOUSE TO BE DEMOLISHED IN PHASE I 17. REMOVE EXISTING CEMENT BOARD SIDING, REPLACE WITH HARDIBOARD SIDING PER DRAWINGS, INSTALL NEW SHEATHING AND HOUSE WRAP AS REQUIRED.
- 18. RECONSTRUCT WALL SEE DRAWINGS.
- 19 SEE PLANS FOR DEMOLITION AND NEW CONSTRUCTION IN THIS AREA ON WEST ELEVATION.
- 20 REPLACE EXISTING CROWN MOULDING 21. REPLICATE AND REPLACE EXISTING BRACKETS
- 22 REMOVE AND REPLACE BOTTOM 7 PIECES OF LAP SIDING TO MATCH THIS ELEVATION
- 23. REPLACE CORNER BOARDS WITH PVC
- 24. REMOVE WINDOWS, INFILL WITH CONSTRUCTION TO MATCH ADJACENT WALLS
- 25. THIS SASH TO BE REPLACED WITH SPANDREL GLASS WINDOW AND CLOSED UP FROM INSIDE
- 26 INFILL VOID WITH MISSING FRAMING AND TRIM 27. RECONSTRUCT ROTTEN PORCH EDGE TO MATCH
- 28 SALVAGE TRIM FOR REUSE ON MAIN BUILDING
- 29. REPLACE MISSING PORCH SOFFIT TO MATCH
- 30. REPLACE INSIDE FACE OF PORCH BEAM WHERE MISSING
- 31. REMOVE AND REPLACE CEMENT BOARD WITH NEW SIDING PER DRAWINGS.

## **GENERAL NOTES**

1. REPLACE MISSING FOUNDATION VENTS WITH SIMILAR DESIGN

Davis Williams Architects Associated



624 South McDonough St Montgomery, Alabama 36104 (334) 834-2038 (334) 834-1037 www.BDWarchitects.com



THE BENJAMIN WINSTON WALKER HOUSE

103

RESTORATIONS & ADDITION TO

o. Description Date
IISSUED FOR REVIEW 04/21

**EXTERIOR ELEVATIONS** RENOVATION

A0.6